IPC-Tags
BARCODE LABELS FOR TEXTILES

QuickSeal Label Application Instructions


LB-40375, LB-4031,
LB-41575, LB-4021

3 Keys to Success in QuickSeal Label Application

• Time



LIGHT GARMENTS
or FABRICS
3 – 5 Seconds



HEAVY FABRICS
6 Seconds

• Temperature



TOP HEAT
375°- 385° F 195° C

BOTTOM HEAT
300˚- 330˚F 165˚ C



• Pressure



2" x 4" PLATEN
28 - 32 psi (air)

3" x 5" PLATEN
53 - 60 psi (air)

4” x 6” PLATEN
85 – 95 psi (air)

3-1/4" x 5" GOOSENECK
58 - 65 psi (air)

25 – 28 lbs./sq. inch
inter-platen pressure



For more information on QuickSeal application, heat seal machine settings, trouble shooting:
see our website ipc-tags.com and click on ‘Resources and Links’.

For ordering labels, or more information contact Amber@ipc-tags.com