

3 Keys to Success with


L- and LB- 4010, 4021, 4031, 41575, 41108

Quick Seal Barcode Label Heat Seal Application


• **Time**



LIGHT GARMENTS
or FABRICS
 3-5 Seconds



HEAVY GARMENTS
 6 Seconds




• **Temperature**



TOP HEAT
 375-385°F 204°C

Optional
BOTTOM HEAT
 330°-350° F 165°-176° C




• **Pressure**



2" x 4" PLATEN 25 - 30 psi
3" x 5" PLATEN 50 - 60 psi
4" x 6" PLATEN 70 - 85 psi
3-1/4" x 5" GOOSENECK 55 - 65 psi

25-28 lbs./inch²
 inter-platen pressure



Note that labels must be applied to a smooth, flat surface. (Don't apply over seams, stitching, etc.)

For ordering labels, prices, or more information contact Amber@ipc-tags.com

Customer Service: 817-714-8400 • Order Fax: (817) 887-1725 • Corporate (972) 822-0934